
My MachineDrum forgot that it has a +Drive

Posted by Plip - 2013/04/17 01:13

Hey guys,

I updated to os v 1.63 today (which was actually on my md before, I just thought I could fix some messed up settings) and lost my +Drive on the way.

The Update seemed to go well and after the machinedrum rebooted and I went into my global menu, the snapshot directory under files was gone and with it my sample bank selector.

As the machine is exactly 5 days old and everything was well before the update, I suspect a software related problem.

Selftest states dram and sram are okay.

Did anyone else came across that problem or can give me advice how to get my machine back to full functionality?:unsure:

Thanks for your help!

Plip

=====

Re:My MachineDrum forgot that it has a +Drive

Posted by heckadecimal - 2013/04/17 01:37

Reinstall the firmware.

=====

Re:My MachineDrum forgot that it has a +Drive

Posted by Plip - 2013/04/17 02:14

I did!

I even downgraded to v1.50f and back to v1.63.

No snapshot menus anymore.

Test still says everything is fine.

I contacted Elektron's support. Let's see if they come up with a solution...

Plip

=====

Re:My MachineDrum forgot that it has a +Drive

Posted by REOvolt - 2013/04/17 13:33

I had the same problem with a new unit. No +drive from day one. Support thought it was a loose connection (hardware fault). I returned the unit to the former owner who bought it and never used it. I can ask him how it went after that.

=====

Re:My MachineDrum forgot that it has a +Drive

Posted by Plip - 2013/04/18 00:18

Well, with mine it is different.

Everything was fine at the beginning. I actually switched happily between the snapshots but on the way lost my "factory" presets. Which weren't saved properly on Snap1.

After checking the factory presets on Elektron's website, I realized they obviously have new ones that they don't offer for download.

So the idea was to play the actual os v1.63 over the already existing v1.63 system. Regarding the presets everything went well, but now the snapshot ability is gone.

I really would love to believe in a hardware error, but why does it suddenly appear after the system upgrade? I mean, I didn't even move the machine for the update.

Elektron's support seems to be AWOL. So no help from them till now.

plip

=====

Re:My MachineDrum forgot that it has a +Drive

Posted by REOvolt - 2013/04/18 02:30

Plip wrote:

Well, with mine it is different.

Everything was fine at the beginning. I actually switched happily between the snapshots but on the way lost my "factory" presets. Which weren't saved properly on Snap1.

After checking the factory presets on Elektron's website, I realized they obviously have new ones that they don't offer for download.

So the idea was to play the actual os v1.63 over the already existing v1.63 system. Regarding the presets everything went well, but now the snapshot ability is gone.

I really would love to believe in a hardware error, but why does it suddenly appear after the system upgrade? I mean, I didn't even move the machine for the update.

Elektron's support seems to be AWOL. So no help from them till now.

plip

I emailed the guy and he said they opened it up and couldn't find any loose contacts. The problem is still there....

=====

Re:My MachineDrum forgot that it has a +Drive

Posted by Plip - 2013/04/18 09:44

Thanks for asking him.

Might support my thesis that it is a software issue.

Let's see if Elektron comes up with something.

Plip

=====

Re:My MachineDrum forgot that it has a +Drive

Posted by Plip - 2013/04/19 09:40

Support wants me to send the MD in and that's what I am gonna do as soon as I am back in Europe.

=====

Re:My MachineDrum forgot that it has a +Drive

Posted by moxlust - 2013/09/09 06:50

Hey PLIP,

This same issue has happened to me. Did you get any solutions from Elektron?

I just sent them an email - HOPE I don't have to ship this MD to Sweden...

=====