
Do not use 1.29c for SPS-1

Posted by Toni - 2005/07/05 17:11

Greetings elektrons,

Just found out this from elektron website (concerns 1.29c):

- General -

The SPS-1 could boot believing it was an SPS-1UW and by initiating sample memory remove the bootstrap which can only be restored by factory service.

This affected all versions of OS 1.29, so please upgrade to this one if you are using SPS-1!!!

There is a new OS (1.29d), where this is corrected, available from elektron website. This might not be a big issue; does not happen to all, but I figured I could save someones headache by posting this.

=====

Re: Do not use 1.29c for SPS-1

Posted by glaive - 2005/07/05 17:23

I have removed 1.29c and replaced it with 1.29d. I'll make a news note, too.

=====

Re: Do not use 1.29c for SPS-1

Posted by divi - 2005/07/05 17:29

not a big issue h?? "can only be restored by factory service" sounds pretty serious to me! thanks for the warning

=====

Re: Do not use 1.29c for SPS-1

Posted by Toni - 2005/07/05 17:40

divi wrote:

not a big issue h?? "can only be restored by factory service" sounds pretty serious to me! thanks for the warning
I kind of ment that this probably doesn't happen to all SPS-1's, otherwise 'the elektron-users.com boat' would be sinking with angry threads. Also Elektron themselves didn't underline this, obviously because it does it in some rare situations.
So I guess no need to react too threataded.

=====

Re: Do not use 1.29c for SPS-1

Posted by mr_snugglz - 2005/07/05 18:47

whheeeeeeeew, no problem for me...yikes, that's scary though...

=====

Re: Do not use 1.29c for SPS-1

Posted by MokBor - 2005/07/06 07:08

Damn scary, losing a bootstrap is not ok :-) Then the MD is unable to do anything. Glad i have an UW instead of the normal sps-1 :-D

=====

